



FORCE GAUGE

- Battery operated with power supply.
- **Peak-Hold-Funktion** for detecting the peak value or **Track-Funktion** for continuous measurement display.
- Range: FK10 10N FK25 25N FK50 50N FK100 100N FK250 250N FK500 500N FK 1K 1000N

SKU: 02801-B

Categories: [Test Equipment](#), [Measuring Instruments and Software](#), [Force gauge manual](#)

